

1800 Alta Vista Drive Ottawa ON K1G 4J5 Canada

2019-12-17 CBS Control #: CBS6384 HPFB File #: C1892-100390 REF: H-1920-WIN-L

Ms. Victoria Hurlbut Biologic Products Specialist Regulatory Operations and Regions Branch Health Canada Suite 1625, 16<sup>th</sup> Floor 1505 Barrington Street Halifax, Nova Scotia B3J 3Y6

Dear Ms. Hurlbut:

## Re: Responses to Health Canada Inspection of Licensed Activities at Winnipeg Operations 2019-11-18 to 2019-11-22

The following are the actions undertaken by Canadian Blood Services in response to the observations contained in the Health Canada Exit Notice dated 2019-12-02.

## Section 98 - Personnel

- 1. The training records for a new driver had the following deficiencies:
  - a) The CET for Living Our Brand did not have Section 4-Reviewer Confirmation completed.
    b) Various records requiring performance measurement did not have Section 3-Trainer Confirmation completed.

DEV# 19-001043 was initiated on 2019-11-27.

Records were corrected as per 08 851 Manual of Good Documentation Practices.

A review of all current employee training records in Logistics was performed. Thirty-four (34) documentation deficiencies were identified that will be corrected by 2020-01-31.

A review of SOP 08 553 Deliver Training and associated documentation was completed by the Logistics Manager on 2019-12-11 and will be completed by the Supervisor by 2020-01-31.

## Section 117 - Records

2. Whole Blood Component Assessment/Production Record B 1 (clinic 2018-10-15), processing completion 2018-10-16, was not supervisory reviewed and dated.

MQE-19-000286 initiated on 2019-11-19.

The staff member responsible for the review was made aware of the importance of reviews and documentation of such. The Whole Blood Component Assessment/Production Record-B1 was corrected as per 08 851 Manual of Good Documentation Practices on 2019-11-19.

The Whole Blood Component Assessment/Production Record-B1 is no longer required with the

implementation of the new production methods.

If you require clarification or further information, please do not hesitate to contact the undersigned. Please reference the above CBS control number in any correspondence.

Sincerely,

Carstran Chequet

Dr. Christian Choquet Vice-President Quality & Regulatory Affairs Fax Number: 613-739-2505

cc: Shelley Smyth

A/Supervisor – Blood, Tissues, Organs and Xenografts Regulatory Operations and Regions Branch